

T S F

The same
matter I have
discussed with
you often for

Apr 25¹, Monday, Oct 7, 1921.

Special Work.

I reported at the mill
this morning 6:30 A.M.
In the employment office before
starting time this morning
I noticed a large number of
negros had the pass way to
employment window blocked
so white women had to
squeeze between them to
get by it seems that the
village Police should have
been there to keep the negros
in their place

In #1 mill #3 room I run
A. F. Barnett 12 looms on the
14 S.W. goods it is hard
to tell how they run because
the yarn was crossed between
the lease rods and harness
causing the looms to stop off
The following numbers of looms
on said set #68 temple to
low #67 harness can set wrong
#21 too much power #26 Boss
not rolling harness straps up
equal #23 temple loose
Four of the said looms are
on Tip Seener section who is

Apr 25:1 Monday Oct. 17, 1921.

Special Work.
to high tempered it seems to have a section.

In top spinning room #1 Mill on 19 1/2 yarn the roping seemed to run alright and Mable Cathan 10 side spinner in said room said her sides run alright this morning but in the afternoon they run very bad which makes me believe they dont keep the humidity right.

Some parts of #2 mill weaver room is kept to wet.

In #1 Mill #3 room South end it was 72 dry 70 wet.

75 " 75 " 5 headers cut off over the 3BRW good which is fine work and it rolls up and sticks together when the yarn gets little to wet.

This afternoon it was 76 dry 73 wet
78 " 74 "
79 " 77 "

My looms kept me very busy I didnt see Supts. I only saw the Boss weaver pass through once.
Finished Work 5:50 P.M.